

### Approvals and conformities

EDF (PMUC : Produits et Matériels Utilisables en Centrale)

ISO 3452-2

RCC-M

### MANUFACTURER: Babb Co (FR)

### DESCRIPTION / APPLICATION(S):

Blue thixotropic product for:

1. - Surface evenness test
2. - Research of surface flaws by penetrant testing. Type 2, method A or C, level 2 according ISO 3452-2.

### Companion products: 1. Surface evenness test:

Cleaner: N120, cleaning rags N120

Remover: N106A, cleaning rags N106A, BabbCoSafe 105

Using any other means may "destabilized" Bleu PR2, i.e. may make it liquid.

#### 1. Penetrant testing:

Cleaner: N120, cleaning rags N120

Remover: N106A, cleaning rags N106A

Developer: D-100, R60, D-106

## ***DIRECTIONS FOR USE***

### 1. Surface evenness test :

For surface evenness check of leak-free equipment (valves, etc), use preimpregnated N120 wipes, or, as an alternative, N106A wipes or BabbCoSafe105 to clean surfaces. N120 spray cans with clean rags may be used too. Allow for drying.

Apply a very thin layer of Bleu PR2 on the mobile part. Then, put the mobile and the non-mobile parts in contact, without any rotation.

Pull up the mobile part. Surfaces of the fixed part which were in contact with corresponding surfaces of the mobile part are blue.

Inspect for non blue-colored areas, using a minimum of 500 lux white light illuminance on the surface under inspection, showing non contact areas.

Final cleaning is carried out with N120 pre-impregnated wipes, or, as an alternative, N106 wipes.

Water cleaning is possible, if allowed.

### 1. Penetrant Testing :

Thoroughly clean surface with N120 (recommended) or with cleaning rags moistened with N120. Use a brush, a rag, any convenient means to apply penetrant on the surface to be checked.

Penetration time is of at least 20 to 30 minutes.

Removal of excess penetrant shall be done under adequate visible light 350 lux mini. Remove most of the penetrant with clean, dry rags. To complete removal use cleaning rags N106A if necessary.

Allow 3 to 5 minutes for drying.

Apply a thin, even layer of non aqueous wet developer by spraying only (spray can is the recommended means)

Inspection shall be done under adequate white light (500lux minimum) at the surface of parts. When possible, conditions stated in ISO 3059 should be met (warm light give better results)

Final cleaning may be carried out using cleaning rags N120, cleaning rags N106A, or water if allowed.

## **TECHNICAL CHARACTERISTICS**

---

Very low halogen (fluorine, chlorine, bromine) and sulfur content.

Compatible with all metals and certain synthetic materials.

Appearance ..... blue pasty product

Flash point ..... > 65°C

Viscosity ..... very high, but can be reduced significantly when stirred.

## **PRECAUTIONS FOR USE AND STORAGE**

---

**Transport / Handling:** Refer to Material Safety Data Sheet (MSDS)

**Storage:** Keep away from moisture

Temperature range: 0°C à 50° C

Keep packaging closed after taking out some of the product

**This technical data sheet replaces and cancels the previous one.**

The above details have been compiled to the best of our knowledge. They have, however, an indicative value only and we therefore make no warranties and assume no liability in connection with any use of this information, particularly if a third party's rights are affected by the use of our products. The above information has been compiled based upon tests carried out by SOCOMORE. All data is subject to change as Socomore deems appropriate. The data given is not intended to substitute for any testing you must conduct in order to determine the suitability of the product for your particular purposes. Please check your local legislation applicable to the use of this product. Should you need any further information please contact us.